

FORNER DR-1

TECHNICAL NOTICE

It is our ongoing commitment to excellence that drives us to continually test and inspect our products long after they are released and to relay the results to our customers via our website www.greatplanes.com and inserted updates. It is our sincere hope that the end result is a satisfied customer with a product that brings many hours of enjoyment.

PERFORMANCE ISSUE

We have received some reports regarding failure of the glue joints on the plywood motor mount. Unfortunately, there seems to be no cosmetic indication that the motor mount may be at risk. We are hoping that these occurrences can be kept to a minimum by following the procedure listed below.

Wick thin CA into all the edges and joints of the firewall where indicated in the photo.

